AIRWORTHINESS DIRECTIVE AND MODIFICATION RECORD

Model	A/C Reg.	SN	Year	AIRFRAME	For modifications embodied to the aircraft up to 19-08-2005 refer to the Individual Inspection Logbook belonging to the aircraft.
EC155B1	PH-EQU	6708	2005		

SB Issue Date	SB	AD Issue Date	BLA/MD	EASA-AD DGAC-AD	ACTION	INTERVAL	D. DATE	TYPE	ACTION REQUIRED?	ACTION TAKEN	DATE	MECH
		31-10-2007	1976-01/9		PERIODIEK ONDERHOUD AAN UITRUSTING, INSTRUMENTEN & SYSTEMEN	24 MTH		CHK	NO	SUPERSEDED BY MD NL-2011-002	16-02-2012	ECD
		01-07-2013	NL-2011-002		PERIODIEK ONDERHOUD AAN UITRUSTING, INSTRUMENTEN & SYSTEMEN	24 MTH		CHK	NO	SUPERSEDED BY MD NL-2011-002R1	14-04-2014	ECD
		15-06-2014	NL-2011-002R1		PERIODIEK ONDERHOUD AAN UITRUSTING, INSTRUMENTEN & SYSTEMEN	24 MTH		CHK	YES	INCORPORATED IN COMPONENT RECORD	14-04-2014	ECD
		30-11-2001	1987-30/4		ONDERHOUDSPROGRAMMA			CHK	NO	SUPERSEDED BY MD NL-2010-001	18-11-2011	HHT
		31-07-2002	1992-085/3		FOREIGN AIRWORTHINESS DIRECTIVES			ADM	NO	AD'S INCORPORATED IN AMP	18-11-2011	HHT
		01-07-2010	NL-2010-001		ON-CONDITION MAINTENANCE			ADM	NO	HHT-MP-EC155B1 AMP REFERS	18-11-2011	HHT
		13-07-2010	NL-2010-002		CONTINUING AIRWORTHINESS RECORDS-STATUS OF REPAIRS			ADM	NO	FAR25/JAR25/CS25 LARGE AIRCRAFT ONLY	13-07-2010	HHT
		30-06-1999	1990-42/4		TECHNISCHE ADMINISTRATIE EN UITSTEL PERIODIEK ONDERHOUD			CHK	NO	SUPERSEDED BY MD NL-2011-001	18-11-2011	HHT
		14-02-2011	NL-2011-001		TECHNISCHE ADMINISTRATIE EN UITSTEL PERIODIEK ONDERHOUD			CHK	NO	INCORPORATED IN AMP	30-01-2012	HHT
	Honeywell SB KT-76A-7	31-07-1998	1998-078 (AB)		ATC TRANSPONDER KT-76A			MOD	NO	TYPE NOT FITTED	25-08-2008	HHT
		15-01-2004	2004-002		HALON FIRE EXTINGUISHERS			CHK	NO	N/A BY TYPE FIRE EXTINGUISHER		HHT
12-04-2007	TX 00000375	30-08-2006		2006-0265	MODE C AND S TRANSPONDER CHECK FOR TRANSPONDERS UTILIZING GILHAM ALTITUDE INPUT CODES	24MTH	2-feb-09	CHK	NO	CANCELLED	17-04-2013	EASA
		31-07-2007		HB-2007-295	HORIZONTAL NET SRFW HN1			RFS	NO	RESCUE NET NOT FITTED	20-08-2007	HHT
		11-12-2008		2008-0158R2 NL-2008-001R2	TRT600 MODE S TRANSPONDERS FUNKWERK AVIONICS GMBH		11-sep-08	LIMIT	NO	TYPE NOT FITTED	25-08-2008	HHT
		11-12-2008		2008-0183 NL-2008-004	TRT800A AND TRT800H MODE S TRANSPONDERS FUNKWERK AVIONICS GMBH		11-sep-08	LIMIT	NO	TYPE NOT FITTED	25-08-2008	HHT
		25-08-2008		2008-0159	MODE S TRANSPONDERS HONEYWELL TYPE MST-67A			MOD	NO	TYPE NOT FITTED	25-08-2008	HHT
		11-08-2008		SIB 2008-59	TURBOSHAFT-ENGINE POWERED ROTORCRAFT - ENGINE IN-FLIGHT SHUTDOWN DUE TO ICE AND SNOW INGESTION				YES	RECOMMENDATIONS WHEN METEOROLOGICAL CONDITIONS OCCUR		
07-04-2008	SIL FFS04	18-12-2008 19-02-2009		SIB 2008-68R1 FAA 2009-05-08	NAVIGATION DATA (NAVDATA) SUPPORT OF FREEFLIGHT SYSTEMS (TRIMBLE) NAVIGATION SYSTEMS				NO	SOFTWARE UPDATED BY AVIONIC STAUBING	20-05-2009	HHT
		22-01-2009		SIB 2009-01	JET FUEL CONTAINING FAME (BIO-DIESEL)				NO	WITHDRAWN	17-09-2015	EASA
17-02-2009	EASB04A008	18-02-2009		2009-0035-E	NAVIGATION-UNS-1D NAVIGATION SYSTEM		20-feb-09		NO	UNS-1D NAVIGATION SYSTEM NOT FITTED	18-02-2009	HHT
		26-05-2009		SIB2009-06R1	ROCKWELL-COLLINS GPS RECEIVER		20-jun-09	MOD	NO	WITHDRAWN	17-09-2015	EASA
		15-05-2013		2009-08-01	HONEYWELL NZ-2000 NAVIGATION COMPUTERS AND IC-800(E) INTERGRATED AVIONICS COMPUTERS			MOD	NO	CONCERNED MODELS NOT FITTED	12-11-2009	HHT
		07-01-2009		NM-10-12	HONEYWELL NZ-2000 PRIMUS EPIC FLIGHT MANAGEMENT SYSTEM			FMS	NO	CONCERNED MODELS NOT FITTED	08-01-2010	HHT
		07-01-2010		NM-10-13	HONEYWELL NZ-2000 PRIMUS EPIC FLIGHT MANAGEMENT SYSTEM			SOFT-WARE	NO	CONCERNED MODELS NOT FITTED	08-01-2010	HHT
29-07-1977 31-01-2003	AT150 No. 1 AT150 No.6	08-09-2009		2009-0200	AT-150 TRANSPONDERS		22-sep-10	MOD	NO	TYPE NOT FITTED	08-09-2009	HHT
		25-11-2009		2009-0251-E	PORTABLE HALON 1211 FIRE EXTINGUISHERS		28-nov-09	REPL	NO	N/A BY P/N FIRE EXTINGUISHER	25-11-2009	HHT
15-12-2009	FIRE FIGHTING 26-115	15-12-2009		2009-0262	PORTABLE HALON 1211 FIRE EXTINGUISHERS		29-jan-10	REPL	NO	N/A BY P/N FIRE EXTINGUISHER	15-12-2009	HHT
22-12-2009	SICLI ASB26-001	22-12-2009		2009-0278	PORTABLE HALON 1211 FIRE EXTINGUISHERS		29-jan-10	REPL	NO	N/A BY S/N FIRE EXTINGUISHER	23-12-2009	HHT
21-12-2009	L'HOTELLIER 863520-26-001	23-12-2009		2009-0277	PORTABLE HALON 1211 FIRE EXTINGUISHERS		6-feb-10	REPL	NO	N/A BY P/N FIRE EXTINGUISHER	23-12-2009	HHT
27-01-2010	FIRE FIGHTING 26-115C	27-01-2010		2009-0262R1	PORTABLE HALON 1211 FIRE EXTINGUISHERS		29-jan-10	REPL	NO	SUPERSEDED BY AD 2009-0262R1	15-12-2009	HHT
21-12-2009	L'HOTELLIER 863520-26-001	05-02-2010		2009-0277R1	PORTABLE HALON 1211 FIRE EXTINGUISHERS		6-jul-10	REPL	NO	N/A BY S/N FIRE EXTINGUISHER	05-02-2010	HHT
31-03-2010	FIRE FIGHTING 26-116	31-03-2010		2010-0062	PORTABLE HALON 1211 FIRE EXTINGUISHERS		14-aug-10	REPL	NO	SUPERSEDED BY AD 2010-0062R1	31-03-2010	HHT

AIRWORTHINESS DIRECTIVE AND MODIFICATION RECORD

Model	A/C Reg.	SN	Year	AIRFRAME	For modifications embodied to the aircraft up to 19-08-2005 refer to the Individual Inspection Logbook belonging to the aircraft.
EC155B1	PH-EQU	6708	2005		

SB Issue Date	SB	AD Issue Date	BLA/MD	EASA-AD DGAC-AD	ACTION	INTERVAL	D. DATE	TYPE	ACTION REQUIRED?	ACTION TAKEN	DATE	MECH
17-05-2010	FIRE FIGHTING 26-116B	17-05-2010		2010-0062R1	PORTABLE HALON 1211 FIRE EXTINGUISHERS		14-aug-10	REPL	NO	N/A BY P/N FIRE EXTINGUISHER	31-03-2010	HHT
		20-01-2010		SIB 2010-02	HONEYWELL (BENDIX/KING) NAVIGATION SYSTEMS-INCORRECT MAGNETIC VARIATIONS IN DATA BASE			SOFT-WARE	NO	TYPE NOT FITTED	20-01-2010	HHT
		22-01-2010		CE-10-14	HONEYWELL (BENDIX/KING) NAVIGATION SYSTEMS-INCORRECT MAGNETIC VARIATIONS IN DATA BASE			SOFT-WARE	NO	TYPE NOT FITTED	22-01-2010	HHT
		26-03-2010		CE-10-22	HONEYWELL (BENDIX/KING) NAVIGATION SYSTEMS-MODIFICATION LEVELS			SOFT-WARE	NO	TYPE NOT FITTED	26-03-2010	HHT
		09-12-2009		SIB 2009-28	FLIGHT DATA RECORDER AND COCKPIT VOICE RECORDER SYSTEMS SERVICEABILITY	DAILY		CHK	NO	SUPERSEDED BY R1	21-06-2010	HHT
		08-01-2015		SIB 2009-28R1	FLIGHT DATA RECORDER AND COCKPIT VOICE RECORDER SYSTEMS SERVICEABILITY	DAILY		CHK	NO	AUTOMATIC SELFTEST INCORPORATED IN SSCVFDR	08-01-2015	HHT
		09-12-2009		SIB 2009-29	FLIGHT DATA RECORDER AND COCKPIT VOICE RECORDER DORMANT FAILURES	6/12 MTH		CHK	NO	SUPERSEDED BY R1	21-06-2010	HHT
		08-01-2015		SIB 2009-29R1	FLIGHT DATA RECORDER AND COCKPIT VOICE RECORDER DORMANT FAILURES	6/12 MTH		CHK	NO	INCORP INSPECTION SHEETS	21-06-2010	HHT
		30-07-2010		SIB 2010-22	CRASH POSITION INDICATOR CPI 503 series ELT - LIMITED DEPLOYMENT ALTITUDE				YES	PILOTS INFORMED NOT TO DEPLOY ABOVE 200FT	04-08-2010	FOM
08-06-2011 18-04-2011	SIN 2322-S-25 COBHAM SB 02/2011	21-05-2015		2011-0093	CHELTON EMERGENCY LOCATOR TRANSMITTER (ELT) ANTENNA, P/N 21-41		4-dec-15	MOD/ REPL	NO	SUPERSEDED BY AD 2011-0103		
08-06-2011 18-04-2011	SIN 2322-S-25 COBHAM SB 02/2011	27-05-2011		2011-0103	CHELTON EMERGENCY LOCATOR TRANSMITTER (ELT) ANTENNA, P/N 21-41		4-dec-15	MOD/ REPL	NO	MODIFIED ANTENNA I/A/W SB 02/2011	28-09-2011	HHT
		07-06-2011		SAIB SW-11-39	FREEFLIGHT SYSTEMS (TRIMBLE) NAVIGATION SYSTEMS, SOFTWARE UPDATED			SOFT-WARE	NO	SIL FFS08 C/W PREVIOUS,SOFTWARE VERSION N	28-09-2011	HHT
18-01-2011	COBHAM SIL 102-2100-34-	01-07-2011		PAD 11-064	IND201 RADIO ALTIMETERS			MOD	NO	SUPERSEDED BY PAD 11-064R1	15-09-2011	HHT
13-07-2011	COBHAM SIL 102-2100-34-	26-09-2011		PAD 11-064R1	IND201 RADIO ALTIMETERS			MOD	NO	SUPERSEDED BY AD 2011-0239	27-09-2011	HHT
13-07-2011	COBHAM SIL 102-2100-34-	15-12-2011		2011-0239	IND201 RADIO ALTIMETERS			MOD	NO	N/A BY P/N INDICATOR (INCORPORATED IN PFD)	27-09-2011	HHT
03-08-2011	ACSS TN8008359	17-01-2012		2012-02-08	ACSS TRAFIC ALERT AND TCAS SYTEMS, LLC		13-3-2015	MOD	NO	N/A BY TYPE TCAS	17-02-2012	HHT
19-04-2012	GOODYEAR 2012-32-001	05-06-2012		ANAC 2012-05-01	GOODYEAR TYRES, GOODYEAR DO BRASIL			CHK/ REPL	NO	ALL TYRES MARKED MADE IN USA	22-03-2013	HHT
31-01-2012	KIDDE GAVINER	10-03-2016		2012-0037	HAND OPERATED FIRE EXTINGUISHER			MOD	NO	N/A BY MODEL FIRE EXTINGUISHER	09-03-2012	HHT
		31-01-2013		2013-0020	SAFETY BELTS / TORSO RESTRAINT SYSTEMS			CHK/ REPL	NO	SUPERSEDED BY AD 2013-041R1		
		26-02-2013		2013-0020R1	SAFETY BELTS / TORSO RESTRAINT SYSTEMS		14-8-2013	CHK/ REPL	NO	SUPERSEDED BY AD 2013-041R2	28-05-2013	HHT
		11-07-2013		2013-0020R2	SAFETY BELTS / TORSO RESTRAINT SYSTEMS		14-8-2013	CHK/ REPL	NO	SUPERSEDED BY AD 2013-041R3	28-05-2013	HHT
		21-03-2014		2013-0020R3	SAFETY BELTS / TORSO RESTRAINT SYSTEMS		14-8-2013	CHK/ REPL	NO	SUPERSEDED BY AD 2013-041R4	28-05-2013	HHT
		05-09-2014		2013-0020R4	SAFETY BELTS / TORSO RESTRAINT SYSTEMS		14-8-2013	CHK/ REPL	NO	IDENTIFIED BY DESIGN APPROVAL HOLDER	28-05-2013	HHT
		13-05-2014		PAD 14-078	EQUIPMENT & FURNISHINGS - Emergency Locator Transmitter - Modification			MOD	NO	N/A BY S/N 406AF ELT	16-06-2014	HHT
		16-10-2014		PAD 14-078	EQUIPMENT & FURNISHINGS - Emergency Locator Transmitter - Modification			MOD	NO	PAD 14-78 WITHDRAWN	16-10-2014	EASA
		30-05-2014		PAD 14-089	EQUIPMENT & FURNISHINGS - Emergency Floatation System - Rotorcraft Flight Manual (Supplement) Limitation			RFM (S)	NO	SUPERSEDED BY AD 2013-0188		
		28-08-2014		2014-0188	EQUIPMENT & FURNISHINGS - Emergency Floatation System - Rotorcraft Flight Manual (Supplement) Limitation			RFM (S)	NO	SUPERSEDED BY AD 2014-0188R1	08-09-2014	HHT
		07-11-2014		2014-0188R1	EQUIPMENT & FURNISHINGS - Emergency Floatation System - Rotorcraft Flight Manual (Supplement) Limitation		1-12-2014	RFM (S)	NO	SUPERSEDED BY AD 2014-0188R2	08-09-2014	HHT

AIRWORTHINESS DIRECTIVE AND MODIFICATION RECORD

Model	A/C Reg.	SN	Year	AIRFRAME	For modifications embodied to the aircraft up to 19-08-2005 refer to the Individual Inspection Logbook belonging to the aircraft.
EC155B1	PH-EQU	6708	2005		

SB Issue Date	SB	AD Issue Date	BLA/MD	EASA-AD DGAC-AD	ACTION	INTERVAL	D. DATE	TYPE	ACTION REQUIRED?	ACTION TAKEN	DATE	MECH
		25-03-2015		2014-0188R2	EQUIPMENT & FURNISHINGS - Emergency Floatation System - Rotorcraft Flight Manual (Supplement) Limitation		1-12-2014	RFM (S)	NO	SUPERSEDED BY AD 2014-0188R3	09-06-2015	HHT
		08-07-2015		2014-0188R3	EQUIPMENT & FURNISHINGS - Emergency Floatation System - Rotorcraft Flight Manual (Supplement) Limitation		1-12-2014	RFM (S)	NO	SUPERSEDED BY AD 2014-0188R4	09-06-2015	HHT
		15-07-2015		2014-0188R4	EQUIPMENT & FURNISHINGS - Emergency Floatation System - Rotorcraft Flight Manual (Supplement) Limitation		1-12-2014	RFM (S)	NO	SEASTATE 6 - INSERTED APPX 2 IN RFM	09-06-2015	HHT
16-02-2017	34-028	10-11-2015		SIB 2015-24	NAVIGATION - Standby Compass - Check of the standby compass lighting power supply harness SIRS SB CE2-A26-34-001R4		9-11-2016	CHK	YES	CHECK IDENTIFICATION LEAD ASSEMBLY		
27-07-2011	KIDDE GAVINER	08-03-2016		2016-0044	KIDDE GRAVINER SINGLE HEAD AUTOMATIC FIRE EXTINGUISHERS			CHK	NO	N/A BY P/N FIRE EXTINGUISHERS	02-02-2016	HHT
21-08-2003	ASB31A008	03-09-2003		F-2003-323	INDICATING AND RECORDING SYSTEMS - Modification of the Power Supply to Landing Gear PCB 10 and 11 ALPHA			MOD	NO	C/W ASB31A008 AND MOD 0739C22	19-08-2005	HAM
21-08-2003	ASB31A005R1 SB31A008	03-09-2003		F-2002-515R1	INDICATING AND RECORDING SYSTEMS - Landing Gear Extension Inoperative	15HR		MOD	NO	C/W ASB31A005 AND MOD 0739C22	19-08-2005	HAM
08-09-2003	ASB52A015	01-10-2003		F-2003-372	DOORS - Modification of support and adjustment of microswitch on cabin sliding door			MOD	NO	C/W MOD 0753C48	19-08-2005	EC
13-01-2004	ASB67003R1	26-05-2004	BLA2003-106/2	2004-5339 F-2003-322R1	ROTOR FLIGHT CONTROLS - Introduction of Double Locking of Flight Control Stop Screws by Sealing the Screws	100HR / 500HR / 1 YR		MOD	NO	C/W ASB67A003R1 AND MOD0767B58	19-08-2005	HAM
19-04-2004	ASB67A004	26-05-2026		2004-0734 F-2004-013R1	ROTORS FLIGHT CONTROL - Collective low pitch value reduction			MOD	NO	C/W ASB67A004 AND MOD 0767B62	19-08-2005	EC
19-04-2004	ASB67A005	17-05-2004		2004-0734 F-2004-013R1	ROTORS FLIGHT CONTROL - Restriction Prohibiting Intentional Autorotation Flight			MOD	NO	C/W ASB67A004	19-08-2005	EC
19-05-2004	ASB24A011	21-07-2004		2004-7527 F-2004-057R1	ELECTRICAL POWER - Electrical and Electronic Panels - Protection of Panel 12 Alpha Wiring	50HR / 100HR		MOD	NO	C/W ASB 24A011 AND MOD 0739C28	19-08-2005	HAM
03-06-2004	ASB62A006	07-07-2004		2004-7031 F-2004-106	MAIN ROTOR - Check for Correct Positioning of the Filler Wedge of the Tenon at the Main Rotor Blade Tip	660HR		CHK	NO	C/W ASB62A006 LIMIT SERVICE LIFE OF BLADES TO 10K HRS S/N >809	19-08-2005	HAM
18-06-2004	ASB32A004R1	07-07-2004		2004-7026 F-2004-099	LANDING GEAR - Wheel Brake Hydraulic Hose Bursting	AFTER EACH ADJUSTMENT		CHK	YES	C/W ASB32A004R1 AND FOLLOW AMM, C/W HHT 19-10-2012	17-01-2017	HHT
22-07-2004	ASB52A013	15-09-2004		2004-9373 F-2003-345R2	DOORS - Cabin Sliding Door	PRE FLIGHT		MOD	YES	C/W ASB52A013 AND MOD 0753C49	30-03-2017	HHT
22-07-2004	ASB53A008	15-09-2004		2004-9367 F-2004-156	Rev 0 FUSELAGE - Improvement of sliding door fittings and rails			MOD	NO	C/W ASB53A008	19-08-2006	HAM
29-07-2004	ASB04A007	15-09-2004		2004-9375 F-2004-060R1	LIMITATION - Never Exceed Speed (VNE)			MOD	NO	C/W ASB04A007 AND MOD 0753C59 / 0752C18	19-08-2005	HAM
29-07-2004	ASB52A016R1	15-09-2004		2004-9376 F-2004-107R1	DOORS - Checking the Condition of Sliding Door Forward Fittings and the Position of Sliding Door Upper Roller, Forward Centering Pins and Centering Pin Receptacles	AFTER EACH ADJUSTMENT		CHK	YES	C/W ASB52A016R1 AND FOLLOW AMM	17-01-2017	HHT
04-08-2004	TA63A007	24-10-2004	BLA2004-114	2004-9029 F-2004-154	MAIN ROTOR DRIVE - Anomaly Affecting the MGB Oil Low Pressure Indication			CHK	NO	C/W TA63A007	19-08-2006	HAM
02-05-2005	ASB52A017	15-09-2004		2004-9368 F-2004-157	DOORS - Reinforcing the Supports of Forward Centering Pins and Receptacles on Sliding Doors and Sliding Door Jambs			MOD	NO	C/W ASB53A017	19-08-2006	HAM
22-07-2005	ASB05006R2	10-11-2004		2004-10845 F-2004-180	MAINTENANCE CHECKS Check and Replacement of Baggage Compartment Fire Extinguisher and Engine Fire Extinguishers			MOD	NO	C/W ASB05006R1 AND MOD 0726B24 / 0726B22 REPLACED BY ASB05A006R3	19-08-2006	HAM
10-11-2004	ASB05A005	24-11-2004		2004-11117 F-2004-023R1	AD Rotor Drive(s)- Check of Main Gearbox (MGB) Base Plate	15HR @ 2600 CYC		CHK	NO	SUPERSEDED BY AD 2006-0101		
04-08-2005	ASB05A007	09-11-2005		2005-6390 F-2005-181	TIME LIMITS - MAINTENANCE CHECKS - Check of the MGB Planet Gear Carrier	50HR		CHK	NO	C/W ASB05A007 INCORPORATED IN AMP REPLACED BY ASB05A007R1 & AD 2007-0288-E		HHT
	AT 05A011	14-09-2005		2005-6227 F-2005-144R1	MAINTENANCE CHECKS - Tail Rotor Blade Check	15HR / 7D		CHK	NO	SUPERSEDED BY AD 2006-0099		
21-11-2005	ASB29A001	10-2-2006 19-07-2006		2006-0042-E F-2006-042	HYDRAULIC POWER - Check of Flexible Hydraulic Pipes and their Attachment Clamps			MOD	NO	C/W ASB29A001	19-08-2006	HAM
13-12-2005	ASB52A018R2	24-02-2006		2006-0052-E	EAD Doors - Cabin Sliding Doors	15HR / 100HR/600HR		CHK	NO	C/W SB52A018 INCORPORATED AMP, FOR REPLACEMENT CHECK COMP. RECORD	14-06-2016	HHT

AIRWORTHINESS DIRECTIVE AND MODIFICATION RECORD

Model	A/C Reg.	SN	Year	AIRFRAME	For modifications embodied to the aircraft up to 19-08-2005 refer to the Individual Inspection Logbook belonging to the aircraft.
EC155B1	PH-EQU	6708	2005		

SB Issue Date	SB	AD Issue Date	BLA/MD	EASA-AD DGAC-AD	ACTION	INTERVAL	D. DATE	TYPE	ACTION REQUIRED?	ACTION TAKEN	DATE	MECH
21-12-2005	ASB04A006	31-08-2006		2006-0098 F-2004-046	LIMITATIONS - To Prevent any Untimely Opening of the Hoist Hook				NO	N/A NOT FITTED	05-05-2006	HAM
10-01-2006	ASB29A004	01-02-2006		2006-0021 F-2005-119R1	HYDRAULIC POWER - Sand in Hydraulic Power System Coolers			CHK	NO	N/A NOT FITTED	19-08-2006	HAM
20-01-2006	ASB67A007	01-02-2006		2006-0019 F-2005-127R1	ROTOR FLIGHT CONTROLS - Check of the Collective Pitch Lever Restraining Tab	AFTER EACH ADJUSTMENT		CHK	NO	SUPERSEDED BY ASB 67A007R1	19-08-2006	HAM
01-02-2006	ASB64A001R1	03-04-2006		2006-0078	AD Tail Rotor- Blade Tuning Weights				NO	N/A FOR TYPE B1	05-05-2006	HAM
15-02-2006	ASB05A013	20-02-2006		2006-0051-E	TAIL ROTOR - Tail Rotor Pitch Control Rod Bearing	110HR		CHK	NO	SUPERSEDED BY AD 2006-0258R1-E		
16-02-2006	ASB05A005R1	24-04-2006		2006-0101 F-2004-023R2	AD Rotor Drive(s)- Check of Main Gearbox (MGB) Base Plate	15HR @ 2600 CYC		CHK	NO	INCORPORATED IN AMP,C/W ASB05A005R1 AT 2600 CYC	28-07-2008	HAM
01-03-2006	SB05A011	24-04-2006		2006-0099	MAINTENANCE CHECKS - Tail Rotor Blade Check	15HR / 7D		CHK	NO	INCORPORATED IN AMP, C/W SB05A011 FOLLOW AMM		HHT
06-03-2006	FM REV07	14-07-2006		2006-0214	AD Indicating System/Rotor Drive - Main Gear Box- Low Oil Pressure Warning	PRE FLIGHT		CHK	YES	BEFORE START REF FM REV07	30-03-2017	PILOT
27-06-2006	ASB25A064	22-08-2006		2006-0252	EQUIPMENT AND FURNISHINGS - "Hoist Operator's Belt" Snap Hook Locking				NO	SUPERSEDED BY AD 2010-0014	01-09-2006	HAM
10-07-2006	ASB05A014	17-05-2006		2006-0126-E	TIME LIMITS – MAINTENANCE CHECKS - Check of the CPT 609 Crash Position Transmitter Beacon Antenna				NO	SUPERSEDED BY AD 2007-0224	18-05-2006	HAM
29-08-2006	ASB05A015	22-08-2007		2006-0258R1-E	TIME LIMITS - MAINTENANCE CHECKS - Maintaining the oil level in the tail gearbox (TGB) at its maximum level. Checking the tail rotor hub (TRH) pitch change control rod bearing for absence of play if metal chips are detected at the magnetic pl			CHK	NO	SUPERSEDED BY AD 2008-0147-E	28-07-2008	HHT
22-09-2006	ASB76A001	16-10-2007		2006-0256R1	ENGINE CONTROLS - Modification of "OFF/IDL/FLT" selector lifting interlocks on 12 ALPHA panel			MOD	NO	C/W ASB76A001 AND MOD 0739C36 C/W	21-11-2006	HAM
06-12-2006	ASB62A014	22-11-2006		2006-0368E	MAIN ROTOR - Check of the Rotor Mast / Hub Nut	660HR		CHK	NO	SUPERSEDED BY ASB62A014R1	06-12-2006	HAM
19-02-2007	ASB67A010	11-04-2007		2007-0099	ROTOR FLIGHT CONTROLS Return to conformity of tail rotor servo-controls			CHK	NO	N/A BY S/N	16-04-2007	HAM
01-06-2007	ASB25A085	06-06-2007		2007-0159-E	EQUIPMENT AND FURNISHINGS - Electrical Bonding of the Hoist Cut-Off Connector "24 Delta"			CHK	NO	FIXED PARTS HOIST NOT FITTED	06-12-2007	HHT
09-08-2007	ASB05A016R1	19-09-2007		2007-0256	CHECK BELT BUCKLE FOR CRACK			CHK	NO	SUPERSEDED BY ASB05A016R2	06-12-2007	HHT
06-09-2007	ASB05A014R2	10-09-2007		2007-0224R1	TIME LIMITS – MAINTENANCE CHECKS - Check of the CPT 609 Crash Position Transmitter Beacon Antenna	1		CHK	NO	N/A CPI FITTED	06-12-2007	HHT
28-09-2007	ASB05A017	28-09-2007		2007-0259-E	TIME LIMITS – MAINTENANCE CHECKS - Fittings Attaching the Upper Fin on the Fenestron	55HR		CHK	NO	SUPERSEDED BY AD 2007-0259R1	30-05-2008	HHT
13-11-2007	ASB05A007R1	15-11-2007		2007-0288-E	TIME LIMITS - MAINTENANCE CHECKS - Check of the MGB Planet Gear Carrier	50HR		CHK	NO	SUPERSEDED BY ASB 05A007R2	05-05-2008	HHT
13-11-2007	ASB05A016R2	19-09-2007		2007-0256	CHECK BELT BUCKLE FOR CRACK			CHK	NO	C/W ASB 05A016R2	12-12-2007	HHT
10-12-2007	SB 05-008R1				TIME LIMITS - MAINTENANCE CHECKS - Visual Inspection of the RH and LH Engine Oil Return Pipes in the MGB Compartment	110 HR		CHK	NO	INCORPORATED IN AMP	30-01-2012	HHT
25-03-2008	TX00000451				MAINTENANCE CHECKS- Double Bearing of the Tail Rotor Pitch Control rod	1		CHK	YES	CHK Daily oil level in TGB and maintain at maximum level, INCORP. IN AMP	30-03-2017	HHT
11-04-2008	ASB05006R3	10-11-2004		2004-180	MAINTENANCE CHECKS Check and Replacement of Baggage Compartment Fire Extinguisher and Engine Fire Extinguishers			MOD	NO	C/W ASB05006R1 AND MOD 0726B24 / 0726B22	19-08-2006	HAM
07-05-2008	ASB63A011	14-05-2008		UF-2008-004	CHECK of the Main Gearbox Casing			CHK	NO	SUPERSEDED BY AD 2011-0127	08-05-2008	HHT
26-05-2008	ASB25A087	27-05-2008		2008-0096-E	CPI 503 CRASH POSITION INDICATOR BEACON			CHK	NO	ASB25A087 C/W	24-06-2008	HHT
11-06-2008	TX 00000462				SICMA 169/170 SERIES PASSENGER SEATS		11-jul-08	MOD	NO	TYPE NOT FITTED	24-06-2008	HHT
11-06-2008	TX 00000463				SICMA 169/170 SERIES PASSENGER SEATS		11-sep-08	CHK	NO	TYPE NOT FITTED	24-06-2008	HHT
17-06-2008	TX 00000464				MAINTENANCE CHECKS- interference between engine oil return pipe and bracket on transmission deck, RH side			CHK	NO	SUPERSEDED BY TX 00000467	03-07-2008	HHT
03-07-2008	TX 00000467				MAINTENANCE CHECKS- interference between engine oil return pipe and bracket on transmission deck, RH side			CHK	YES	CHK I/A/W MTC 20.07.03.408 PARA 4.7	17-01-2017	HHT
11-08-2008	ASB05A015R2	01-08-2008		2008-0147-E	TIME LIMITS - MAINTENANCE CHECKS - Maintaining the oil level in the tail gearbox (TGB) at its maximum level. Checking the tail rotor hub (TRH) pitch change control rod bearing for absence of play if metal chips are detected at the magnetic plug	15HR / 7D 110HR		CHK	NO	SUPERSEDED BY ASB05A015R3 AND AD 2009-0247	12-11-2009	HHT
26-08-2008	05-012				TIME LIMITS - MAINTENANCE CHECKS checks for absence of Corrosion/Fretting on the Attach Beams of the Main Rotor Head	36 MTH		CHK	YES	CHK I/A/W SB 05-012	17-01-2017	HHT
25-10-2005	SB 62-003R2				MAIN ROTOR - INSTALLATION OF CONING STOPS			MOD	NO	MODIFIED I/A/W SB 62-003R2	23-01-2009	HHT

AIRWORTHINESS DIRECTIVE AND MODIFICATION RECORD

Model	A/C Reg.	SN	Year
EC155B1	PH-EQU	6708	2005

AIRFRAME

For modifications embodied to the aircraft up to 19-08-2005 refer to the Individual Inspection Logbook belonging to the aircraft.

SB Issue Date	SB	AD Issue Date	BLA/MD	EASA-AD DGAC-AD	ACTION	INTERVAL	D. DATE	TYPE	ACTION REQUIRED?	ACTION TAKEN	DATE	MECH
01-06-2005	SB 62-009				MAIN ROTOR - STRONG WIND START ENVELOPE EXTENSION TO 55 Kts			MOD	NO	MODIFIED I/A/W SB 62-009	23-01-2009	HHT
04-12-2007	SB 52-024				Reinforcement of upper and lower sliding door locking fingers - Corresponds to DWG 365A088863			MOD	NO	FOUND C/W PREVIOUS, CANCELLING 1200 HRS OTL OF LOCKING FINGERS	23-01-2009	HHT
25-05-2007	SIL 07-1	09-10-2008		PAD 08-113	ROCKWELL COLLINS TDR 94/94D MODE S TRANSPONDER			CHK/ MOD	NO	SUPERSEDED BY PAD 08-113R1 P/N 622-9210-007	23-01-2009	HHT
02-09-2008	TDR-94/94D-34-505/506/507	09-10-2008		PAD 08-114	ROCKWELL COLLINS TDR 94/94D MODE S TRANSPONDER			MOD/ RPL	NO	SUPERSEDED BY PAD 08-114R1 P/N 622-9210-007	23-01-2009	HHT
02-09-2008	TDR-94/94D-34-505/507	13-10-2008		PAD 08-112	ROCKWELL COLLINS TDR 94/94D MODE S TRANSPONDER			MOD/ RPL	NO	SUPERSEDED BY PAD 08-112R1	23-01-2009	HHT
02-09-2008	TDR-94/94D-34-505/507	03-03-2009		PAD 08-112R1	ROCKWELL COLLINS TDR 94/94D MODE S TRANSPONDER			MOD/ RPL	NO	SUPERSEDED BY PAD 08-112R2	03-03-2009	HHT
27-09-2007	SIL 07-2	04-08-2009		PAD 08-112R2	ROCKWELL COLLINS TDR 94/94D MODE S TRANSPONDER			MOD/ RPL	NO	SUPERSEDED BY AD 2010-0003	04-08-2009	HHT
27-09-2007	SIL 07-2	11-01-2010		2010-0003	ROCKWELL COLLINS TDR 94/94D MODE S TRANSPONDER			MOD/ RPL	NO	SUPERSEDED BY AD 2010-0003R1	04-08-2009	HHT
27-09-2007	SIL 07-2	05-01-2010		2010-0003R1	ROCKWELL COLLINS TDR 94/94D MODE S TRANSPONDER			MOD/ RPL	NO	SUPERSEDED BY AD 2010-0003R2	04-08-2009	HHT
25-05-2007	SIL 07-1	03-03-2009		PAD 08-113R1	ROCKWELL COLLINS TDR 94/94D MODE S TRANSPONDER			CHK/ MOD	NO	SUPERSEDED BY AD 2009-0097	23-01-2009	HHT
02-09-2008	TDR-94/94D-34-505/506/507	03-03-2009		PAD 08-114R1	ROCKWELL COLLINS TDR 94/94D MODE S TRANSPONDER			MOD/ RPL	NO	SUPERSEDED BY AD 2009-0173	03-03-2009	HHT
25-05-2007	SIL 07-1	22-04-2009		2009-0097	ROCKWELL COLLINS TDR 94/94D MODE S TRANSPONDER			CHK/ MOD	NO	SUPERSEDED BY AD 2010-0067	23-01-2009	HHT
02-09-2008	TDR-94/94D-34-505/506/507	05-08-2009		2009-0173	ROCKWELL COLLINS TDR 94/94D MODE S TRANSPONDER			MOD/ RPL	NO	SUPERSEDED BY AD 2009-0173R1	05-08-2009	HHT
25-5-2007 04-05-2010	SIL 07-1 34-021R1	12-04-2010		2010-0067	ROCKWELL COLLINS TDR 94/94D MODE S TRANSPONDER		26-apr-11	CHK/ MOD	NO	WIRING CHECKED I/A/W TDR94 SIL07-1	23-01-2009	HHT
02-09-2008	TDR-94/94D-34-505/506/507	30-09-2010		2009-0173R1	ROCKWELL COLLINS TDR 94/94D MODE S TRANSPONDER			MOD/ RPL	NO	A/C EQUIPED WITH THALES ADU 3000	05-08-2009	HHT
16-09-2009	TDR-94/94D-34-508	06-10-2010		2010-0204	ROCKWELL COLLINS TDR 94/94D MODE S TRANSPONDER		20-okt-11	MOD/ RPL	NO	A/C EQUIPED WITH THALES ADU 3000	06-10-2010	HHT
16-09-2009	TDR-94/94D-34-508	07-07-2011		2010-0204 CORRECTION	ROCKWELL COLLINS TDR 94/94D MODE S TRANSPONDER		20-okt-11	MOD/ RPL	NO	A/C EQUIPED WITH THALES ADU 3000	06-10-2010	HHT
16-09-2009	TDR-94/94D-34-506/507/ 508/509	03-05-2012		SIB 2012-08	ROCKWELL COLLINS TDR 94/94D MODE S TRANSPONDER			MOD	NO	TRANSPONDER INSTALLATION CHECKED I/A/W SIB 2012-08 & ROCKWELL COLLINS SIL 12-1 C/W	28-05-2013	HHT
27-09-2007	SIL 07-2	17-09-2014		2010-0003R2	ROCKWELL COLLINS TDR 94/94D MODE S TRANSPONDER			MOD/ RPL	NO	AIRCRAFT WITH TAKE-OFF SPEED >100KTS ONLY	04-08-2009	HHT
22-10-2008	32-008				LANDING GEAR -Main Landing Gear: Wheel Brake Hose			CHK	NO	N/A BY MANUFACTERING DATE LH AND RH HOSE	13-11-2008	HHT
25-02-2009	ASB67A007R1	01-02-2006		2006-0019 F-2005-127R1	ROTOR FLIGHT CONTROLS - Check of the Collective Pitch Lever Restraining Tab	AFTER EACH ADJUSTMENT		MOD	NO	SUPERSEDED BY AD 2011-0154	01-03-2010	HHT
25-02-2009	SB 67-009	01-02-2006		2006-0019 F-2005-127R1	ROTOR FLIGHT CONTROLS - Hinged, spring-loaded collective lever locking blade		31-dec-09	MOD	NO	SUPERSEDED BY AD 2011-0154 and Revision1 of SB 67-009	01-03-2010	HHT
30-03-2009	ASB04A009	01-04-2009		2009-0078-E	VIP 4-SEAT BENCHES			LIMIT	NO	SUPERSEDED BY AD 2009-0078R1	01-04-2009	HHT
28-07-2009	IN 2068-I-34	20-04-2009		2009-05-08	TRIMBLE OR FREEFLIGHT SYSTEMS 2101 I/O APPROACH PLUS GPS NAVIGATION SYSTEM		20-okt-09	MOD	NO	SOFTWARE UPDATED BY AVIONIC STAUBING	20-05-2009	HHT
27-03-2009	SB 24-017				INTERFERENCE BETWEEN STARTER-GENERATOR CABLE AND A FIRE DETECTOR SUPPORT	600		CHK	NO	SUPERSEDED BY REV 1	14-07-2014	HHT
12-05-2009	ASB04A001	10-06-2009		2009-0122	SIREN LOAD RELEASE UNITS LOAD JAMMED ON THE CARGO HOOK IN THE OPEN POSITION		24-jun-09	CHK/ MOD	NO	SUPERSEDED BY AD 2009-0122R1	10-06-2009	HHT
24-06-2009	ASB04A009R1	30-06-2009		2009-0078R1	VIP 4-SEAT BENCHES			LIMIT	NO	TYPE NOT FITTED	01-04-2009	HHT
05-06-2009	42315-489-01R1	12-06-2009		2009-0124	EQUIPMENT / FURNISHING - LIVESAVING SYSTEMS D-LOK HOOK OF THE RESCUEHOIST - INSPECTION / REPLACEMENT			CHK	NO	SUPERSEDED BY AD 2009-0148-E	12-06-2009	HHT
05-06-2009	42315-489-01R1	09-07-2009		2009-0148-E	EQUIPMENT / FURNISHING - LIVESAVING SYSTEMS D-LOK HOOK OF THE RESCUEHOIST - INSPECTION / REPLACEMENT			CHK	NO	SUPERSEDED BY AD 2009-0179-E	12-06-2009	HHT

AIRWORTHINESS DIRECTIVE AND MODIFICATION RECORD

Model	A/C Reg.	SN	Year	AIRFRAME	For modifications embodied to the aircraft up to 19-08-2005 refer to the Individual Inspection Logbook belonging to the aircraft.
EC155B1	PH-EQU	6708	2005		

SB Issue Date	SB	AD Issue Date	BLA/MD	EASA-AD DGAC-AD	ACTION	INTERVAL	D. DATE	TYPE	ACTION REQUIRED?	ACTION TAKEN	DATE	MECH
20-07-2009	25-094				EMERGENCY FLOATATION GEAR CHECK OF INSTALLED "42G" UNITS		20-jan-10	CHK	NO	CHECKED WIRING I/A/W SB 25-094 TO PREVENT UNTIMELY ACTIVATION	01-03-2010	HHT
06-08-2009	ASB04A010	11-08-2009		2009-0179-E	EQUIPMENT / FURNISHING - LIVESAVING SYSTEMS D-LOK HOOK OF THE RESCUEHOIST - INSPECTION / REPLACEMENT			CHK	NO	SUPERSEDED BY AD 2009-0183-E	12-06-2009	HHT
06-08-2009	ASB04A010	14-08-2009		2009-0183-E	EQUIPMENT / FURNISHING - LIVESAVING SYSTEMS D-LOK HOOK OF THE RESCUEHOIST - INSPECTION / REPLACEMENT			CHK	NO	SUPERSEDED BY FAA 2010-03-02, EASA AD 2009-0183-E IS CANCELLED	11-02-2010	HHT
18-08-2009	SIN 2082-S-25 TFS 00000541				SICMA 169/170 SERIES PASSENGER SEATS, INCORPORATION OF SICMA SB 169-25-012			MOD	NO	MODEL SEAT NOT FITTED	12-11-2009	HHT
15-10-2009	IN 2058-I-25				CPI 503 CRASH POSITION INDICATOR BEACON			CHK	NO	INSTRUCTIONS FOR PROGRAMMING, C/W PREVIOUS	15-10-2009	HHT
30-10-2009	24-016				ELECTRICAL POWER - CHECKING UNIT 37 ALPHA		30-okt-11	CHK	NO	CHECK DIODE NUTS I/A/W SB 24-016	01-03-2010	HHT
09-11-2009	ASB05A015R3	13-11-2009		2009-0247	TIME LIMITS - MAINTENANCE CHECKS - Maintaining the oil level in the tail gearbox (TGB) at its maximum level. Checking the tail rotor hub (TRH) pitch change control rod bearing for absence of play if metal chips are detected at the magnetic plug	15HR / 7D 110HR		CHK	NO	SUPERSEDED BY AD 2011-0105	25-02-2011	HHT
16-11-2009	ASB05A007R2	15-11-2007		2007-0288-E	TIME LIMITS - MAINTENANCE CHECKS - Check of the MGB Planet Gear Carrier	50HR		CHK	NO	SUPERSEDED BY ASB 05A007R3	08-12-2009	HHT
26-11-2009	34-019				NAVIGATION- Maintenance of radar antenna slaving units				YES	C/W SB 34-019 BEFORE 3000H/3Y FOR P/N 4000504-0301, S/N 1097		
27-06-2006 26-06-2006	ASB 25A064 ASB 25A069	26-01-2010		2010-0014	HOIST OPERATORS BELT SNAP HOOK LOCKING			MOD	NO	NO HOIST INSTALLED	26-01-2010	HHT
27-01-2010	ASB05A017R1	26-02-2010		2007-0259R1	TIME LIMITS – MAINTENANCE CHECKS - Fittings Attaching the Upper Fin on the Fenestron	55HR		CHK	NO	SUPERSEDED BY E ASB 05A017R2	30-05-2008	HHT
18-01-2010	25-096				EQUIPMENT AND FURNISHINGS - Emergency flotation gear: Untimely deployment.		18-jul-10	CHK	NO	SB 25-096 C/W	01-03-2010	HHT
11-01-2010	29-008				HYDRAULIC POWER Check of the Hydraulic Pipe Installation	600 HR		CHK	YES	INSPECTED I/A/W SB 29-008	17-01-2017	HHT
06-08-2009	EASB01.00.54	20-01-2010		FAA-2010-03-02	EQUIPMENT / FURNISINGS - D-LOK HOOK OF THE RESCUE HOIST - INSPECTION / REMOVAL FROM SERVICE / REPLACEMENT			CHK	NO	D-LOK TYPE HOOK NOT FITTED	11-02-2010	HHT
04-02-2010	ASB52A028	11-03-2010		2010-0040	CHECK FOR CORRECT OPERATION OF THE PILOT AND COPILOT DOOR JETTISONING SYSTEM		25-mei-10	CHK	YES	INITIAL INSPECTION C/W, REPEAT BY EVERY DOOR INSTALLATION	01-03-2010	HHT
15-03-2010	31-015R1				CHECK OF THE CENTRAL WARNING PANEL	600 HR	15-mrt-12	CHK	YES	INCORPORATED IN COMPONENT RECORD	25-09-2013	HHT
22-3-2010 08-04-2010	25A100 IN 2175-I-25	23-03-2010		2010-0052-E	EQUIPMENT AND FURNISHINGS - External Life Raft: Check of the mooring line attachment point		25-jun-10	CHK	NO	EXTERNAL LIFE RAFT P/N 245432-0 OR 245434-0 NOT FITTED	23-03-2010	HHT
18-05-2010	25-094R1				EMERGENCY FLOATATION GEAR CHECK OF INSTALLED "42G" UNITS		18-nov-10	CHK	NO	NO SPECTROLAB SX 16 PROVISIONS INCORPORATED	27-05-2010	HHT
15-06-2010	EASB63A007	16-06-2010		2010-0116-E	MAIN ROTOR DRIVE - Main Gearbox Oil Low Pressure Switch Connection.		18-sep-10	CHK	YES	INSPECTED I/A/W EASB 63A007	21-06-2010	HHT
		27-08-2010		2010-0181	TIME LIMITS/MAINTENANCE CHECKS - Airworthiness Limitation Section - Amendment/ Implementation, New Partnumbers		10-okt-10	P/N	NO	Incorporated in MSM revision RN12	27-08-2010	HHA
12-05-2009	ASB04A001 ASB05A022	27-10-2010		2009-0122R1	SIREN LOAD RELEASE UNITS LOAD JAMMED ON THE CARGO HOOK IN THE OPEN POSITION		24-jun-09	CHK/ MOD	NO	NO CARGO HOOK FITTED	10-06-2009	HHT
01-04-2010	29-009				REPLACING THE HYDRAULIC SAS MANIFOLD OUTLET PRESSURE PIPE BY HOSE		25-aug-12	MOD	NO	CHANGED PIPE I/A/W SB 29-009	18-11-2012	HHT
29-04-2010	31-017				REPLACEMENT OF AB BJE MODULE IN UNIT 50 ALPHA		29-apr-11	REPL	NO	SB 31-017 C/W	25-02-2011	HHT
01-10-2010	31-016				UMS/HUMS CHANGE FOR COMPLIANCE WITH JAR-OPS3			MOD	YES	SOFTWARE UPDATE		
27-10-2010	ASB62A014R1	22-11-2006		2006-0368E	CHECK OF THE ROTOR MAST / HUB NUT	660 HR		CHK	NO	SUPERSEDED BY AD 2006-0368R1	06-12-2006	HAM
18-11-2010	ASB56A003	07-12-2010		2010-0257	IMPROVED WINDOW JETTISON SYSTEM ON HINGED CABIN DOORS		30-jun-11	MOD	NO	N/A SLIDING DOORS FITTED	18-11-2010	HHT
27-10-2010	ASB62A014R1	02-12-2010 08-12-2010		2006-0368R1E	CHECK OF THE ROTOR MAST / HUB NUT	660 HR		CHK	NO	N/A MOD 0762B88 C/W	06-12-2006	HAM
03-12-2010	EASB05A017 R2	26-02-2010		2007-0259R1	TIME LIMITS – MAINTENANCE CHECKS - Fittings Attaching the Upper Fin on the Fenestron	55HR	31-dec-11	CHK	NO	SUPERSEDED BY AD 2011-0108	25-02-2011	HHT
07-12-2010	53-029				UPPER FIN FITTINGS REPLACEMENT		31-dec-11	MOD	NO	SUPERSEDED BY SB 53-029R1		

AIRWORTHINESS DIRECTIVE AND MODIFICATION RECORD

Model	A/C Reg.	SN	Year	AIRFRAME	For modifications embodied to the aircraft up to 19-08-2005 refer to the Individual Inspection Logbook belonging to the aircraft.
EC155B1	PH-EQU	6708	2005		

SB Issue Date	SB	AD Issue Date	BLA/MD	EASA-AD DGAC-AD	ACTION	INTERVAL	D. DATE	TYPE	ACTION REQUIRED?	ACTION TAKEN	DATE	MECH
10-03-2011	53-029R1	07-06-2011		2011-0108	UPPER FIN FITTINGS REPLACEMENT		31-dec-11	MOD	NO	PERFORMED MOD 754B40 SB 53-029R1	28-09-2011	HHT
18-03-2011	SIN 2308-S-53				TGB TUBE - MISSING WASHER OF A SPACER				NO	CHECKED I/A/W SIN 22308-S-53	28-09-2011	HHT
21-03-2011	65-006R1				TGB CONTROL SHAFT GUIDE BUSH REPLACEMENT		21-mar-2012	MOD	NO	PERFORMED MOD 0765B58 I/A/W SB 65-006R1	28-09-2011	HHT
11-04-2011	05-021				10 BLADE TAIL ROTOR HUB VISUAL INSPECTION	110HR		CHK	NO	SUPERSEDED BY ASB 05A021R1		
03-05-2011	ASB53A031				DRAINING TANK BOX AREA		03-may-13	MOD	NO	SUPERSEDED BY ASB 53A031R1		
16-05-2011	ASB05A015R4 ASB05A022	31-05-2011		2011-0105	TIME LIMITS - MAINTENANCE CHECKS - Maintaining the oil level in the tail gearbox (TGB) at its maximum level. Checking the tail rotor hub (TRH) pitch change control rod bearing for absence of play if metal chips are detected at the magnetic plug	15HR / 7D 110HR	14-sep-11	CHK	NO	SUPERSEDED BY AD 2011-0117		
09-12-2010	EASB05A017 R2	07-06-2011		2011-0108	TIME LIMITS – MAINTENANCE CHECKS - Fittings Attaching the Upper Fin on the Fenestron, UPPER FIN REPLACEMENT	55HR	31-dec-11	CHK	NO	PERFORMED MOD 754B40 I/A/W EASB 05A017R2	28-09-2011	HHT
22-06-2011	05-023				EMERGENCY FLOATATION GEAR - CHECK OF IMMERSION PROBE		22-jun-12	CHK	NO	CHECKED I/A/W SB 05-023	28-09-2011	HHT
16-05-2011	ASB05A015R4 ASB05A022	24-06-2011		2011-0117	TIME LIMITS - MAINTENANCE CHECKS - Maintaining the oil level in the tail gearbox (TGB) at its maximum level. Checking the tail rotor hub (TRH) pitch change control rod bearing for absence of play if metal chips are detected at the magnetic plug	15HR / 7D 110HR	14-sep-11	CHK	NO	SUPERSEDED BY ASB 05A022R1		
07-05-2008	ASB63A011	01-07-2011		2011-0127	MAIN GEARBOX CASING - INSPECTION/REPAIR			CHK	NO	CHECK FOR SEALING WITHIN 15 HRS	08-05-2008	HHT
17-05-2011	25-105				CRACKS ON THE BACKREST OF A TWO-SEAT BENCH, SICMA AERO SEAT SB 169-25-11	6MTH		CHK/ MOD	NO	FOUND N/A BY P/N SEAT BENCHES	28-09-2011	HHT
20-07-2011	SIN 2354-S-53				ATTACHMENT FITTINGS OF THE MGB COWLINGS	100/600 HR			NO	INCORPORATED IN AMP	10-08-2013	HHT
20-07-2011	05-021R1	26-07-2011		2011-0144	10 BLADE TAIL ROTOR HUB VISUAL INSPECTION	55HR		CHK	NO	SUPERSEDED BY AD 2012-0227	31-10-2011	HHT
16-05-2011 13-07-2011	ASB05A015R4 ASB05A022R1	24-06-2011		2011-0117	TIME LIMITS - MAINTENANCE CHECKS - Maintaining the oil level in the tail gearbox (TGB) at its maximum level. Checking the tail rotor hub (TRH) pitch change control rod bearing for absence of play if metal chips are detected at the magnetic plug	15HR / 7D 110HR	14-sep-11	CHK	NO	SUPERSEDED BY ASB 05A015R5 AND AD 2011-0145		
25-07-2011 13-07-2011	ASB05A015R5 ASB05A022R1	02-08-2011		2011-0145	TIME LIMITS - MAINTENANCE CHECKS - Maintaining the oil level in the tail gearbox (TGB) at its maximum level. Checking the tail rotor hub (TRH) pitch change control rod bearing for absence of play if metal chips are detected at the magnetic plug	15HR / 7D 110HR	14-sep-11	CHK	NO	SUPERSEDED BY ASB 05A022R2	30-01-2012	HHT
25-2-2009 19-07-2010	ASB67A007R1 67-009R1	22-08-2011		2011-0154	ROTOR FLIGHT CONTROLS - Check of the Collective Pitch Lever Restraining Tab, REVISION1 OF SB 67-009		5-sep-11	CHK	NO	SUPERSEDED BY AD 2011-0154 CORRECTION 22-SEP-2011		
21-09-2011	ASB53A031R1	30-09-2011		2011-0190	DRAINING TANK BOX AREA		14-okt-13	MOD	NO	SUPERSEDED BY REV 2	25-09-2013	HHT
25-2-2009 19-07-2010	ASB67A007R1 SB67-009R1	22-09-2011		2011-0154	ROTOR FLIGHT CONTROLS - Check of the Collective Pitch Lever Restraining Tab, REVISION1 OF SB 67-009		5-sep-11	CHK	NO	MODIFIED I/A/W SB 67-009 PREVIOUS & FOUND R1 N/A	28-09-2011	HHT
05-02-2008	21-013				AIR DISTRIBUTION FAN REPLACEMENT			MOD	NO	MOD 0721C05 C/W I/A/W SB 21-013	28-09-2011	HHT
	Mod 07 71C39				AIR INLET SCREEN LOCKWIRE			MOD	NO	LOCKWIRE INSTALLED I/A/W MOD 07 71C39 & AMM 53-53-00-961	16-11-2011	HHT
08-12-2011	ASB05A007R3	15-11-2007		2007-0288-E	TIME LIMITS - MAINTENANCE CHECKS - Check of the MGB Planet Gear Carrier	50HR		CHK	NO	SUPERSEDED BY AD 2007-0288R1	28-12-2011	HHT
08-12-2011	ASB05A007R3	09-01-2012		2007-0288R1	TIME LIMITS - MAINTENANCE CHECKS - Check of the MGB Planet Gear Carrier and Terminating MOD 0763C52	50HR		CHK	NO	C/W ASB05A007 INCORPORATED IN AMP	28-12-2011	HHT
17-01-2012	SIN 2406-S-65				Visual Check of the Double Bearing of the Tail Gearbox control shaft/rod assembly			CHK	NO	C/W I/A/W ASB 05A022R1	29-01-2012	HHT
14-05-2012	ASB25A114	16-05-2012		2012-0084	EQUIPMENT AND FURNISHINGS - EADS SOGERMA Flight Crew Seats		16-aug-12	CHK	NO	SUPERSEDED BY ASB 25A114R1 & AD2012-0206	25-05-2012	HHT
22-03-2012	SIN 2426-S-25R1				EQUIPMENT AND FURNISHINGS - AMSAFE safety belt buckle	3 MTH		CHK	NO	FOUND N/A BY MANUFACTERER BELTS	25-05-2012	HHT
		04-06-2012		2012-0098-E	ROTORCRAFT FLIGHT MANUAL - Emergency Procedures - Rush Revision			AMEN D	NO	FLIGHT MANUAL AMENDED	05-06-2012	HHT
04-07-2012	ASB05A022R2	02-08-2011		2011-0145	TIME LIMITS - MAINTENANCE CHECKS - Maintaining the oil level in the tail gearbox (TGB) at its maximum level. Checking the tail rotor hub (TRH) pitch change control rod bearing for absence of play if metal chips are detected at the magnetic plug	15HR / 7D 55HR	14-sep-11	CHK	NO	SUPERSEDED BY AD 2012-0170	19-10-2012	HHT

AIRWORTHINESS DIRECTIVE AND MODIFICATION RECORD

Model	A/C Reg.	SN	Year	AIRFRAME	For modifications embodied to the aircraft up to 19-08-2005 refer to the Individual Inspection Logbook belonging to the aircraft.
EC155B1	PH-EQU	6708	2005		

SB Issue Date	SB	AD Issue Date	BLA/MD	EASA-AD DGAC-AD	ACTION	INTERVAL	D. DATE	TYPE	ACTION REQUIRED?	ACTION TAKEN	DATE	MECH
		07-08-2012		2012-0148	ROTORCRAFT FLIGHT MANUAL - Operating Limitations Section - Amendment		13-sep-12	AMEND	NO	AD Inserted in RFM section 2.1	08-08-2012	HHT
25-07-2011 04-07-2012	ASB05A015R5 ASB05A022R2	31-08-2012		2012-0170	TIME LIMITS - MAINTENANCE CHECKS - Maintaining the oil level in the tail gearbox (TGB) at its maximum level. Checking the tail rotor hub (TRH) pitch change control rod bearing for absence of play if metal chips are detected at the magnetic plug	15HR / 7D 55HR	14-sep-11	CHK	NO	SUPERSEDED BY ASB 05A022R3	22-03-2013	HHT
09-08-2012	ASB25A114R1	02-10-2012		2012-0206	EQUIPMENT AND FURNISHINGS - EADS SOGERMA Flight Crew Seats			CHK	NO	FOUND N/A BY MANUFACTERER SEATS	21-09-2012	HHT
20-07-2011	05-021R1	29-10-2012		2012-0227	10 BLADE TAIL ROTOR HUB VISUAL INSPECTION	55HR		CHK	NO	INSPECTED I/A/W SB 05-021R1, INCORPORATED IN AMP	02-11-2012	HHT
28-11-2012	33-011				LIGHTS - Anticollision light on top of the fin			CHK	NO	INSPECTED I/A/W SB 33011	08-04-2013	HHT
02-02-2009	33-007R1				LIGHTS - Anticollision light on top of the fin			MOD	NO	MODIFIED I/A/W SB 33-007R1	08-04-2013	HHT
08-11-2012	65-007R1				TAIL ROTOR DRIVE - Replacing the control rod bearing MOD 0765B57			MOD	NO	SUPERSEDED BY R2	22-03-2013	EC
08-11-2012	65-007R1				TAIL ROTOR DRIVE - Reposition lockwire			MOD	NO	SUPERSEDED BY R2	22-03-2013	HHT
07-03-2005	63-006				MAIN ROTOR DRIVE - Modified Safetying of the Oil Pressure Switch Union at the Outlet of the MGB Twin Pump			MOD	NO	MODIFIED I/A/W SB 63-006	08-04-2013	HHT
05-03-2013	25-106				EQUIPMENT AND FURNISHINGS - Baggage compartment			MOD	NO	LABELED AFFIXED I/A/W SB 25-106	28-05-2013	HHT
25-06-2013	ASB05A022R3	31-08-2012		2012-0170	TIME LIMITS - MAINTENANCE CHECKS - Maintaining the oil level in the tail gearbox (TGB) at its maximum level. Checking the tail rotor hub (TRH) pitch change control rod bearing for absence of play if metal chips are detected at the magnetic plug	15HR / 7D 55HR	14-sep-11	CHK	NO	SUPERSEDED BY AD 2012-0170R1	22-03-2013	HHT
04-07-2014	05-024R1				TIME LIMITS - MAINTENANCE CHECKS - FLIGHT CONTROLS - Optimatisation of flight control maintenance	7200 FH 10/14 YRS	31-aug-15	CHK	NO	DUE FROM DATA PLATE DATE 08-2005, INCORPORATED IN AMP	09-12-2015	HHT
21-08-2013	05-025				TIME LIMITS - MAINTENANCE CHECKS - FUSELAGE - Optimatisation of maintenance effective for the structure of EC155 helicopters	6000 FH 8/14 YRS	31-aug-19	CHK	NO	SUPERSEDED BY SB 05-025R1	25-09-2013	HHT
27-07-2009	53-021R1				FLOOR PROTECTION AGAINST CORROSION			MOD	NO	CHECKED, FOUND C/W PREVIOUSLY	25-09-2013	HHT
25-06-2013	ASB05A022R3	18-10-2013		2012-0170R1	TIME LIMITS - MAINTENANCE CHECKS - Maintaining the oil level in the tail gearbox (TGB) at its maximum level. Checking the tail rotor hub (TRH) pitch change control rod bearing for absence of play if metal chips are detected at the magnetic plug	15HR / 7D 55HR	14-sep-11	CHK	NO	SUPERSEDED BY ASB 05A022R4, INCREASED PERIODICITY FROM 55FH TO 110FH	22-03-2013	HHT
25-11-2013	25-117				EQUIPMENT & Furnishings - Improvement of Emergency Floatation Gear Automatic percussion reliability for Aircraft equiped with CVFDR, mod 0745C88 & 0731B76 & 0745C98		25-nov-15	MOD	NO	SUPERSEDED BY R1		
08-11-2013	HRS-SB-030913-1	12-11-2013		PAD 13-165	EQUIPMENT & FURNISHINGS - Crash Position Indicator - Modification Aircraft Flight Manual - Amendment			MOD	NO	SUPERSEDED BY AD 2014-0019		
20-12-2013	ASB25A120	20-03-2014		2014-0072	EQUIPMENT & FURNISHINGS - Emergency Locator Transmitter (ELT) CPI 503-16		3-jul-14	MOD	NO	SUPERSEDED BY EASA AD2015-0075	18-02-2014	HHT
19-12-2013	ASB25A124	22-10-2014		2014-0231	EQUIPMENT & FURNISHINGS - VIP Benches, Modification 365V0800103.00		19-feb-14	CHK	YES	CHECK WITHIN 100FH, NOTE; NOT FITTED ON THIS MOMENT	20-12-2013	HHT
08-11-2013	HRS-SB-030913-1	17-01-2014		2014-0019	EQUIPMENT & FURNISHINGS - Crash Position Indicator - Modification Aircraft Flight Manual - Amendment		2-mrt-14	MOD	NO	PLACARD FITTED, AD INSERTED IN AFM & GUARD FITTED, SUPERSEDED BY AD 2014-0095	18-02-2014	HHT
		27-11-2013		2013-0275R1	EQUIPMENT & FURNISHINGS - Hoist - Test / Replacement GOODRICH HOIST	6 MTH / 300 cyc / 400 Lifts	4-dec-13	CHK	NO	SUPERSEDED BY AD 2014-0201	27-11-2013	HHT
28-01-2014	53-032				FUSELAGE - FENESTRON FIN BALLAST ATTACHMENT MOD 0754B39			MOD		OPTIONAL		
04-04-2014	34C027				NAVIGATION - Adaption of TDR94D transponder wiring - MOD 365R081006.04			MOD	NO	PREVIOUSLY C/W 24/MAY/2013	09-12-2015	HHT
14-04-2014	05-025R1				TIME LIMITS - MAINTENANCE CHECKS - FUSELAGE - Optimatisation of maintenance effective for the structure of EC155 helicopters	6000 FH 8/10/14 YRS	31-aug-15	CHK	NO	8 YRS ITEMS INSPECTED I/A/W SB 05-025, NEXT ITEMS AFTER 10 YRS SINCE NEW, INCORPORATED IN AMP	01-06-2015	HHT
		15-04-2014		2014-0088	COMMUNICATIONS - Cockpit Voice Recorder- Replacement, TEAM-COBHAM AVIONICS		29-oct-15	REPL	NO	N/A BY P/N CVR	29-04-2014	HHT

AIRWORTHINESS DIRECTIVE AND MODIFICATION RECORD

Model	A/C Reg.	SN	Year
EC155B1	PH-EQU	6708	2005

AIRFRAME

For modifications embodied to the aircraft up to 19-08-2005 refer to the Individual Inspection Logbook belonging to the aircraft.

SB Issue Date	SB	AD Issue Date	BLA/MD	EASA-AD DGAC-AD	ACTION	INTERVAL	D. DATE	TYPE	ACTION REQUIRED?	ACTION TAKEN	DATE	MECH
08-04-2014	ASB05A022R4	18-10-2013		2012-0170R1	TIME LIMITS - MAINTENANCE CHECKS - Maintaining the oil level in the tail gearbox (TGB) at its maximum level. Checking the tail rotor hub (TRH) pitch change control rod bearing for absence of play if metal chips are detected at the magnetic plug	15HR / 7D 110HR	14-sep-11	CHK	NO	MODIFIED I/A/W ASB 05A022R1, COMPLY WITH ASB 05A022R4 PARA 3.B.4.b EVERY 110FH AND RECORD VALUE M3, INCORPORATED IN AMP, SUPERSEDED BY AD 2012-0170R2	22-03-2013	HHT
		23-04-2014		2014-0095	EQUIPMENT & FURNISHINGS - Crash Position Indicator - Modification Aircraft Flight Manual - Amendment		31-jan-16	MOD	NO	PLACARD FITTED, AD INSERTED IN AFM & GUARD FITTED, SUPERSEDED BY AD 2014-0095R1	18-02-2014	HHT
28-05-2014	ASB04A012	12-05-2014		2014-0095R1	EQUIPMENT & FURNISHINGS - Crash Position Indicator - Modification Aircraft Flight Manual - Amendment		31-jan-16	MOD	NO	PLACARD FITTED, AD INSERTED IN AFM & GUARD FITTED, SUPERSEDED BY ASB 04A012R1	12-05-2014	HHT
10-04-2014	HRS-SB-03-17-141 REV05	15-05-2014		2014-0125	EQUIPMENT & FURNISHINGS - Crash Position Indicator - Replacement; Aircraft Flight Manual - Amendment			REPL	NO	N/A BY P/N BRU & SIU	22-05-2014	HHT
12-06-2014	ASB05A027				TIME LIMITS - MAINTENANCE CHECKS - External Life Rafts installed in the footsteps	600FH/24MTH	12-sep-14	CHK	NO	SUPERSEDED BY REV 1 AND EASA AD2014-0214	10-08-2014	HHT
25-07-2011 08-04-2014	ASB05A015R5 ASB05A022R4	20-06-2014		2012-0170R2	TIME LIMITS - MAINTENANCE CHECKS - Maintaining the oil level in the tail gearbox (TGB) at its maximum level. Checking the tail rotor hub (TRH) pitch change control rod bearing for absence of play if metal chips are detected at the magnetic plug	15HR / 7D 110HR	14-sep-11	CHK	NO	SUPERSEDED BY EASA AD2016-0097-E	22-03-2013	HHT
09-07-2014	ASB63A012	14-07-2014		2014-0165	MAIN ROTOR DRIVE - Tail Rotor drive flange - Inspection of the Shur-lok nut which retains the tail rotor drive flange of the Main Gearbox POST MOD 0763B64			CHK	NO	SUPERSEDED BY REV 1 AND EASA AD2014-0179	21-08-2014	HHT
21-07-2014	ASB63A012R1	25-07-2014		2014-0179	MAIN ROTOR DRIVE - Tail Rotor drive flange - Inspection of the Shur-lok nut which retains the tail rotor drive flange of the Main Gearbox POST MOD 0763B64			CHK	NO	SUPERSEDED BY EASA AD2014-0179R1	21-08-2014	HHT
21-07-2014	ASB63A012R1	29-07-2014		2014-0179R1	MAIN ROTOR DRIVE - Tail Rotor drive flange - Inspection of the Shur-lok nut which retains the tail rotor drive flange of the Main Gearbox POST MOD 0763B64			CHK	NO	SUPERSEDED BY ASB 63A012R2	12-12-2014	HHT
26-08-2014	ASB04A013	12-09-2014		2014-0204	LIMITATIONS - Energy-Absorbing seats label "DO NOT STOW ANYTHING UNDER THE SEAT"		25-okt-14	MOD	NO	LABELED AFFIXED I/A/W ASB 04A013	15-10-2014	HHT
01-09-2014	ASB05A027R1	24-09-2014		2014-0214	TIME LIMITS - MAINTENANCE CHECKS - External Life Rafts installed in the footsteps	600FH/24MTH	1-okt-14	CHK	NO	NO INTERNAL DEPLOYMENT HANDLE FITTED	10-08-2014	HHT
		08-09-2014		2014-0201	EQUIPMENT & FURNISHINGS - Hoist - Test / Replacement GOODRICH HOIST	24 MTH / 1200 cyc / 1600 Lifts	19-nov-14	CHK	NO	SUPERSEDED BY EASA AD2014-0254	08-09-2014	HHT
23-09-2014	ASB33A013	28-10-2014		2014-0236	LIGHTS - Emergency Lighting Rotorcraft Flight Manual Amendment / Operational Procedure	1 FH	11-dec-14	MOD	NO	AMEND RFM WITH APPENDIX 4.A OF ASB33A013, AND CHECK LIGHTING DAILY, SUPERSEDED BY REV 1	17-11-2014	HHT
29-09-2014	ASB25A128				EQUIPMENT AND FURNISHINGS - Life raft Installation. Improved external life raft deployment controls. MOD 365A084711.01		29-mar-15	MOD	NO	SUPERSEDED BY REV 1		
29-09-2014	25-117R1				EQUIPMENT & Furnishings - Improvement of Emergency Floatation Gear Automatic percussion reliability for Aircraft equiped with CVFDR, mod 0745C88 & 0731B76 & 0745C98		25-nov-15	MOD	NO	SUPERSEDED BY REV 2		
16-10-2014	22-013				AUTO FLIGHT - Yaw trim actuator, Inspection of the yaw trim actuator rod		16-okt-16	CHK	NO	INSPECTED I/A/W SB 22-013	17-01-2017	HHT
		03-11-2014		2014-0240	FUEL - Fuel Supply - Inspection		17-feb-15	CHK	NO	N/A FOR EC155B1	03-11-2014	HHT
		21-11-2014		2014-0254	EQUIPMENT & FURNISHINGS - Hoist - Test / Replacement GOODRICH HOIST	24 MTH / 1200 cyc / 1600 Lifts	24-dec-14	CHK	NO	SUPERSEDED BY EASA AD2015-0069	24-11-2014	HHT
09-12-2014	25-130				EQUIPMENT & FURNISHINGS - EMERGENCY FLOTATION GEAR - REPLACEMENT OF PUSH BUTTONS ON CONTROL UNITS			CHK	NO	SUPERSEDED BY REV 1		
02-02-2015	ASB25A128R1	17-03-2015		2015-0048	EQUIPMENT AND FURNISHINGS - Life raft Installation. Improved external life raft deployment controls. MOD 365A084711.01		2-aug-15	MOD	NO	MOD 365A084711.01 C/W I/A/W ASB 25A128R1	09-06-2015	HHT
27-02-2015	25-131				EQUIPMENT & FURNISHINGS - Life raft container reinforcement for compability with sea state 6			MOD	NO	SUPERSEDED BY REV 1		
27-02-2015	25-133				EQUIPMENT & FURNISHINGS - Reinforcement of the rear floatation gear unit for compability with sea state 6, MOD 0745D25			MOD	NO	MOD 0745D25 C/W I/A/W SB 22-133	09-06-2015	HHT
16-03-2015	29-003R2				HYDRAULIC POWER - Accumulator connection to main rear LH servo-control. MOD 0729B62		1-apr-17	MOD	NO	SUPERSEDED BY REV 3		

AIRWORTHINESS DIRECTIVE AND MODIFICATION RECORD

Model	A/C Reg.	SN	Year	AIRFRAME	For modifications embodied to the aircraft up to 19-08-2005 refer to the Individual Inspection Logbook belonging to the aircraft.
EC155B1	PH-EQU	6708	2005		

SB Issue Date	SB	AD Issue Date	BLA/MD	EASA-AD DGAC-AD	ACTION	INTERVAL	D. DATE	TYPE	ACTION REQUIRED?	ACTION TAKEN	DATE	MECH
23-03-2015	25-131R1				EQUIPMENT & FURNISHINGS - Life raft container reinforcement for compability with sea state 6			MOD	NO	MOD 0745D24 C/W I/A/W SB 25-131R1	09-06-2015	HHT
		30-04-2015		2015-0069	EQUIPMENT & FURNISHINGS - Hoist - Test / Replacement GOODRICH HOIST	24 MTH / 1200 cyc / 1600 Lifts	24-dec-14	CHK	NO	SUPERSEDED BY EASA AD2015-0160	24-11-2014	HHT
		29-04-2015		2015-0068-E	PLACARDS AND MARKINGS - Installation / Replacement			MOD	NO	N/A FOR EC155B1	29-04-2015	HHT
18-03-2015	ASB25A120R1	05-05-2015		2015-0075	EQUIPMENT & FURNISHINGS - Emergency Locator Transmitter (ELT) CPI 503-16		19-aug-15	MOD	NO	N/A BY MOD - 3, PERFORMED PHYSICAL CHECK ON UNIT	02-06-2015	HHT
21-05-2015	SB 24-017R1				INTERFERENCE BETWEEN STARTER-GENERATOR CABLE AND A FIRE DETECTOR SUPPORT	600 FH		CHK	YES	INSPECTED I/A/W SB 24-017, APPLIED PROTECTION AROUND CABLES, PERFORM R1 WITHIN 200FH	17-01-2017	HHT
08-06-2015	25-130R1				EQUIPMENT & FURNISHINGS - EMERGENCY FLOTATION GEAR - REPLACEMENT OF PUSH BUTTONS ON CONTROL UNITS			CHK	NO	N/A BY DATE CODE PUSHBUTTONS 0340	09-12-2015	HHT
16-06-2015	25-117R2				EQUIPMENT & Furnishings - Improvement of Emergency Floatation Gear Automatic percussion reliability for Aircraft equiped with CVFDR, mod 0745C88 & 0731B76 & 0745C98		25-nov-15	MOD	YES	COMPLIANCE OF PARA 3.B.2.a. RECOMMEND BY AH WITHIN 600H/24M, PERORM AT AN CONVENIANT TIME		
22-07-2015	ASB52A032	30-07-2015		2015-0157	DOORS - CREW DOORS - Functional test of the crew door jettisoning system		13-okt-15	CHK	NO	PERFORMED I/A/W ASB52A032	11-10-2015	HHT
		04-08-2015		2015-0160	EQUIPMENT / FURNISHINGS - HOIST - TEST/REPLACEMENT	24 MTH / 1200 cyc / 1600 Lifts	18-9-2015	CHK/ REPL	NO	SUPERSEDED BY EASA AD2015-0226	04-08-2015	HHT
10-08-2015	ASB56A006	13-08-2015		2015-0168	WINDOWS - JETTISONABLE WINDOWS - Check of the press-studs on the window jettisoning system	24MTH	27-sep-15	CHK	YES	PERFORMED I/A/W ASB56A006, INCORPORATE IN AMP	17-01-2017	HHT
		18-11-2015		2015-0226	EQUIPMENT / FURNISHINGS - HOIST - TEST/REPLACEMENT	24 MTH / 1200 cyc / 1600 Lifts	21-12-2015	CHK/ REPL	NO	SUPERSEDED BY EASA AD2015-0226R1	18-11-2015	HHT
		20-11-2015		2015-0226R1	EQUIPMENT / FURNISHINGS - HOIST - TEST/REPLACEMENT	24 MTH / 1200 cyc / 1600 Lifts	21-12-2015	CHK/ REPL	NO	SUPERSEDED BY EASA AD2015-0226R2	23-11-2015	HHT
04-12-2015	ASB33A013R1	28-10-2014		2014-0236	LIGHTS - Emergency Lighting Rotorcraft Flight Manual Amendment / Operational Procedure	1 FH	11-dec-14	MOD	NO	AMENDED RFM WITH APPENDIX 4.A OF ASB33A013R1, AND CHECK LIGHTING DAILY	09-12-2015	HHT
09-12-2015	25-136				EQUIPMENT & FURNISHINGS - 503 HR SMITH CPI BEACON - Replacement of the Interface Unit - MOD 365P086063.00/.03/.10/.13			MOD	NO	SUPERSEDED BY REV 1		
16-07-2009	53-021R1				FUSELAGE - FLOOR PROTECTION AGAINST CORROSION MOD 0753C71			MOD	NO	PERFORMED I/A/W SB 53-021R1	09-12-2015	HHT
10-12-2015	ASB04A012R1	12-05-2014		2014-0095R1	EQUIPMENT & FURNISHINGS - Crash Position Indicator - Modification Aircraft Flight Manual - Amendment		31-jan-16	MOD	NO	SIU CHANGED, PLACARDS, FLM AMENDMENT AND GUARD REMOVED	06-04-2016	HHT
26-01-2016	25-136R1				EQUIPMENT & FURNISHINGS - 503 HR SMITH CPI BEACON - Replacement of the Interface Unit - MOD 365P086063.00/.03/.10/.13			MOD	NO	LIMITATION REQUIRED BY ASB 04A012R1 SUPERSEDED BY MOD 365P086063.00/.03/.10/.13	06-04-2016	HHT
07-03-2016	ASB63A012R2	29-07-2014		2014-0179R1	MAIN ROTOR DRIVE - Tail Rotor drive flange - Inspection of the Shur-lok nut which retains the tail rotor drive flange of the Main Gearbox POST MOD 0763B64			CHK	NO	SUPERSEDED BY EASA AD2014-0179R2	12-12-2014	HHT
		15-03-2016		2015-0226R2	EQUIPMENT / FURNISHINGS - HOIST - TEST/REPLACEMENT	24 MTH / 1200 cyc / 1600 Lifts	21-12-2015	CHK/ REPL	NO	SUPERSEDED BY EASA AD2015-0226R3	23-11-2015	HHT
11-04-2016	ASB63A012R2	29-07-2014		2014-0179R2	MAIN ROTOR DRIVE - Tail Rotor drive flange - Inspection of the Shur-lok nut which retains the tail rotor drive flange of the Main Gearbox POST MOD 0763B64			CHK	YES	INSPECTED DURING INSTALLATION MGB, FOUND MOD 0763B64 NOT C/W, RECHECKED BY 300FH INSPECTION	17-01-2017	HHT
14-04-2016	ASB53A031R2	30-09-2011		2011-0190	DRAINING TANK BOX AREA		14-okt-13	MOD	NO	SUPERSEDED BY ASB 53A031R3	25-09-2013	HHT
15-04-2016	29-003R3				HYDRAULIC POWER - Accumulator connection to main rear LH servo-control. MOD 0729B62		1-apr-17	MOD	YES	Perform para 3.B.2.d. within 660 FH, Recommended to extend flight to -40ºC		
04-05-2016	ASB04A014	23-05-2016		2016-0097-E	LIMITATIONS - CONTROL ROD DOUBLE BEARING - TAIL GEARBOX	15FH / 7D 500FH	1-jun-16	CHK	NO	SUPERSEDED BY EASA AD2016-0097R1		
04-05-2016	ASB04A014	25-05-2016		2016-0097R1	LIMITATIONS - CONTROL ROD DOUBLE BEARING - TAIL GEARBOX	15FH / 7D 500FH	1-jun-16	CHK	NO	SUPERSEDED BY ASB 04A014R1	09-05-2016	HHT
		01-06-2016		2015-0226R3	EQUIPMENT / FURNISHINGS - HOIST - TEST/REPLACEMENT	24 MTH / 1200 cyc / 1600 Lifts	21-12-2015	CHK/ REPL	NO	NO HOIST FITTED	23-11-2015	HHT
03-06-2016	ASB04A014R1	25-05-2016		2016-0097R1	LIMITATIONS - CONTROL ROD DOUBLE BEARING - TAIL GEARBOX	15FH / 7D 500FH	1-jun-16	CHK	NO	SUPERSEDED BY REV 2	07-10-2016	HHT

AIRWORTHINESS DIRECTIVE AND MODIFICATION RECORD

Model	A/C Reg.	SN	Year	AIRFRAME	For modifications embodied to the aircraft up to 19-08-2005 refer to the Individual Inspection Logbook belonging to the aircraft.
EC155B1	PH-EQU	6708	2005		

SB Issue Date	SB	AD Issue Date	BLA/MD	EASA-AD DGAC-AD	ACTION	INTERVAL	D. DATE	TYPE	ACTION REQUIRED?	ACTION TAKEN	DATE	MECH
10-06-2016	24-015				ELECTRICAL POWER - BATTERY COMPARTMENT - INTERFERENCE BETWEEN BATTERY HARNESS AND AIRCRAFT STRUCTURE	TBN		REPL	YES	INSPECTED I/A/W SB 24-015	07-10-2016	HHT
02-06-2016	EASB SA365-65-51	16-06-2016		2016-0115-E	ROTORS - MAIN ROTOR MAST / STARFLEX STAR / MAST CONNECTING BOLTS - REPLACEMENT	2000 FH	18-jun-16	REPL	NO	N/A FOR EC155B1	16-06-2016	HHT
24-08-2016	65-007R2				TAIL ROTOR DRIVE - Replacing the control rod bearing MOD 0765B57			MOD	NO	MOD 0765B57 C/W BY EUROCOPTER	22-03-2013	EC
24-08-2016	65-007R2				TAIL ROTOR DRIVE - Reposition lockwire			MOD	NO	LOCKWIRE REPOSITIONED I/A/W SB 65-007R1	22-03-2013	HHT
21-09-2016	ASB53A031R3	30-09-2011		2011-0190	DRAINING TANK BOX AREA		14-okt-13	MOD	NO	MOD 0745C96, 0753C98, 365A084485.00 C/W I/A/W ASB 53A031R1	25-09-2013	HHT
30-09-2016	25-143				EQUPMENT & FURNISHINGS - PROTECTION OF TRI-BAND ANTENNA MP/N 21-41			MOD	YES	ORDER HEATSHRINK CAP		
28-10-2016	ASB04A014R2	25-05-2016		2016-0097R1	LIMITATIONS - CONTROL ROD DOUBLE BEARING - TAIL GEARBOX	15FH / 7D 500FH	1-jun-16	CHK	NO	SUPERSEDED BY EASA AD 2017-0007	29-11-2016	HHT
15-11-2016	53-036				FUSELAGE - Improvement of resistance to corrosion of blade folding attachment fittings. MOD 0754B47			MOD	YES	AT OPERATORS INITIATIVE		
21-11-2016	05-031				TIME LIMITS - CHECKS - CORROSION PREVENTION	VARIOUS		CHK	YES	AT OPERATORS INITIATIVE		
23-12-2016	SIN 3116-S-63	23-12-2016		SIB 2016-21	MAIN GEARBOX (MGB) - VISUAL CHECK ON THE MGB AND THE FLARED HOUSING			CHK	YES	CHECK MARKINGS AT NEXT OPPORTUNITY		
28-10-2016	ASB04A014R2	13-01-2017		2017-0007	LIMITATIONS - CONTROL ROD DOUBLE BEARING - TAIL GEARBOX - POST MOD 0765B56 & 0765B57 & 07B65B58	15FH / 7D 500FH	1-jun-16	CHK	YES	CHK TGB OIL LEVEL EVERY 7D/15FH, CHK MAGN PLUG EVERY ALF, REPLACE BEARING EVERY 500FH, INCORPORATED IN COMP. RECORD	30-03-2017	HHT
13-03-2017	ASB53A035	31-03-2017		2017-0055	FUSELAGE - COWLINGS & FAIRINGS - INSPECTION OF THE MGB FIXED COWLING FRONT FITTING			CHK	NO	INSPECTED I/A/W ASB 53A035	30-03-2017	HHT
16-03-2017	29-014				HYDRAULIC POWER - Hydraulic Reservoir - Check of the hydraulic pipes at the LH hydraulic reservoir			CHK	YES	RECOMMENDED		